SUBJECT

General: Materiel

Specific: Maintenance Monthly UR Report - June 1966

- 6-1. Hydro pump, Part Number 66YC300, Serial Number 48. Hydro pump leaks at seal drain. Article 359. Total time on item 79.3 hours. Reason for failure Unknown. Negative.
- 6-2. Transponder, C-618T-3, Serial Number 2734. UHF went out after take-off. Article 359. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-3. Dynamotor, Part Number DY107, Serial Number Unknown. UHF Guard inoperative on T/R and G, channel 1 very weak. Article 381. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-4. Wing flap selector valve, Part Number SP-13680-1, Serial Number 153048. Engine rolled back to replace flap selector valve (discrepancy found on maintenance check). Article 381. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-5. Driftsight, Part Number PE500-0156, Serial Number 238. Power changer noisy both directions. Article 381. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-6. Power changer motor, Part Number PE152-1627, Serial Number None. Power changer has noise. Article 348. Total time on item Unknown. Reason for failure Unknown. Negative.
- -6-7. Defroster fan, Part Number SP-M6001B-1A, Serial Number 98. Defroster fan inoperative. Article 348. Total time on item - Unknown, Reason for failure - Unknown. Negative.
- 6-8. EGT Indicator, Part Number SP-BH185R-11D, Serial Number 371. Warning light on EGT indicator appears to be intermittent. Article 381. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-9. Altimeter, Part Number SP-Q409-1, Serial Number 56-16318. Altimeter sticks, lags approximately 250 feet at altitude. Article 349. Total time on item Unknown. Reason for failure Unknown. Negative.
- -6-10. Altimeter, Part Number SP-Q409-1, Serial Number 56-16995. Altimeter sticks. Article 348. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-11. Artifical Horizan Instrument, Part Number SP-Q468-1, Serial Number AF52-
- 40464. Artificial horizon off flag on all the time. Article 349. Total time on Item Unknown. Reason for failure Unknown. Negative.
- 6-12. D.C. Generator, Part Number SP-30B26-21A, Serial Number R61. D.C. Generator appears to have a shorted field erratic voltage output. Article 349. Total time on item 15.6 hours. Reason for failure Unknown. Negative.
- 6-13. Servo Control relay, Part Number 613506-1, Serial Number Unknown. Auto pilot would not engage when turned on. Article 349. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-14. IFF, Part Number 814B, Serial Number 597. IFF inoperative. Article 349. Total time on item Unknown. Reason for failure Unknown. Negative.
- 6-15. Transponder of the lease 2602/D6713 SchraRDRGBB07268990200318919e Eeiver removed, HF radio inoperative. Article 349. Total time on item Unknown. Reason for failure Unknown. Negative.